




√ (100Z /)



A - A



NOTE 1: No burr permitted
NOTE 2: Entire surface except threads should be painted with specified color