



Detailed drawing of end-effector mounting face


$$\begin{aligned} J1 &= \pm 170^\circ \\ J2 &= \pm 120^\circ \\ J3 &= +151^\circ, -120^\circ \\ J4 &= \pm 270^\circ \\ J5 &= +120^\circ, -120^\circ \\ J6 &= \pm 360^\circ \end{aligned}$$
