

Reference Drawings of Cap

A

B

C


D

E

F

G

$\sqrt{Rz\ 100}$ ($\sqrt{\quad}$)



Unless otherwise specified, corners should be C0.1 to C0.5.